

**This Vehicle has**  
**undergone an**  
**RAC Inspection**

128 Point Vehicle Inspection



Vehicle Registration Number: AE19OJS

Date: 06/05/2022

## Summary

Body & Exterior:	OK	Interior Fittings:	OK
Engine Compartment:	OK	Electrical Controls:	OK
Transmission:	OK	Exhaust System:	OK
Front Suspension, Steering & Underframe:	OK	Rear Suspension & Underframe:	OK
Fuel System:	OK	Brakes:	OK
Wheels & Tyres:	OK	Road Test:	OK

## General Details

Registration:	AE19OJS	Mileage:	2851
Make:	Aston Martin	Model:	V8 Vantage
VIN:	SCFSLGAW4KGN02114	Colour:	WHITE



## Body Exterior Fittings

Window & Screen Glass	OK	Bonnet Hinges	OK
Bonnet Catch	OK	Sunroof Operation	N/A
Door Locks/Operation	OK	Fuel Filler Cover/Cap	OK
Number Plates	OK	Convertible Roof Operation	N/A

## Interior Fittings

Seat Adjustment	OK	Boot/Tailgate Lock	OK
Seatbelts	OK	Internal Mirrors	OK

## Engine Compartment

Coolant Level/Condition	OK	Coolant Leaks	OK
Antifreeze	OK	Radiator Cap	N/A
Hoses/Pipes	OK	Auxiliary Drive Belts	OK
Fuel Pump/Pipes	OK	Power Steering Oil Level	N/A
Clutch fluid	N/A	Brake Fluid	OK
Engine Oil Level	OK	Oil Leaking	OK
Engine Mountings	OK	Cold Starting	OK
Fast Idle (cold)	OK	Noise Level (cold)	OK
Excess Fumes/Smoke	OK	Turbo/Supercharger Noisy/Leaks	OK

## Electrical Controls

Starting System/Ignition Lock	OK	Battery Condition	OK
Battery Voltages	OK	Normal	OK
Starting	OK	Charging	OK
Headlights	OK	Sidelights/Running Lights	OK
Rear & Number Plate Lights	OK	Stop Lights	OK
Air Con Operation	OK	ReverseFog Lights	OK
Auxillary Lights	OK	Interior/Panel Lights	OK
Controls/Switches	OK	Instruments	OK
Horn	OK	Windows/Sunroof	OK
Wipers/Washers	OK	Headlamp Wash/Wipe	N/A
Indicator/Hazard Lights	OK	Electric Door Mirrors	OK

## Front Suspension, Steering & Underframe

Engine Underside Leakage	OK	Steering & Ball Joints	OK
Steering Rack/Box	OK	Chassis Members	OK
Power Steering (operation)	OK	Wheel Hubs/Bearings	OK
Springs/Suspension Units	OK	Pipes/Hoses	OK
Dampers (Condition/Leaks)	OK	Gaiters	OK
Sub-Frames/Moutings	OK	Suspension Arms/Mountings	OK
Tie Bars/Anti-Roll Bars	OK		

## Rear Suspension & Underframe

Springs/Suspension Bars	OK	Anti Roll Bars	OK
Dampers/Bushes	OK	Suspension Arms/Fixings	OK
Location Rods/Fixings	OK	Bump Stops/Gaiters	OK
Wheel Hubs/Bearings	OK	Pipes/Hoses	OK
Sub-Frames/Mountings	OK	Chassis Members	OK

## Transmission

Fluid/Oil Leaks	OK	Cables/Adjustments	N/A
Hydraulic System	OK	Linkage (Wear)	OK
Casings	OK	Mountings	OK
Clutch Operation	N/A	Drive Shaft Assembly	OK
Universal/Sliding Joints	OK	Backlash	OK
Gaitors	OK	Propshaft(s)/Fittings	OK
Bearings/Supports	OK		

## Exhaust System

Manifold	OK	Pipes	OK
Catalytic Convertor(s)	OK	Silencer(s)	OK
Heat Shields/Mountings	OK	Joints/Couplings	OK

## Fuel System

Tank	OK	Tank Fixings	OK
Fuel Lines	OK	Breather Pipes	OK
Evidence Of Leaks	OK		

## Brakes

Master Cylinder Security	OK	Fluid Leaks	OK
Servo/Power System	OK	Pedal & Pad Leakage	OK
Discs/Pads (if visible)	OK	Handbrake Operator	OK
Flexible Hoses	OK	Pipes/Connectors	OK

## Wheels & Tyres

Manufacturer	Type	Size	Wheel Type	Tyre Type	Depth	Status
Pirelli	Front Left	255/40 ZR20(101Y)	Alloy	Radial	666	OK
Pirelli	Front Right	255/40 ZR20(101Y)	Alloy	Radial	666	OK
Pirelli	Rear Left	295/35 ZR20(105Y)	Alloy	Radial	565	OK
Pirelli	Rear Right	295/35 ZR20(105Y)	Alloy	Radial	665	OK

## Road Test

Speed Achieved (mph)	60		
Distance Covered (miles)	10		
Final Drive Operation/Noise	OK	Gearbox Operation/Noise Level	OK
Engine Performance	OK	Engine Noise	OK
Excess Smoke	OK	Overheating Evidence	OK
Instrument/Control Function	OK	Suspension Noise	OK
Warning Lights	OK	Steering Effort	OK
Hot Restarting	OK	Auto Changes/Kickdown	OK
Road Holding/Stability	OK	General Steering/Handling	OK
Footbrake Operation	OK	Hand/Park Brake Operation	OK
Cooling Fan Operation	OK		

## Rectifications Required

Item	Comment
------	---------

No items to show...

## Engineers Comments

Undertray preventing visibility to underside leakage

RAC has provided this condition report on the date stated in the report solely for British Car Auctions use.